

Surpahs™ STT-1040 Digital Kitchen Scale User Manual

The user manual can be downloaded through Surpahs™ website at <http://www.surpahs.com>



Scan for shopping and support:



Surpahs™
www.surpahs.com

FEATURES & PECIFICATIONS

- Touch ON function
- Equipped with 4 high precision sensors
- Platform: Tempered Glass
- Display: Positive LCD
- Capacity: 5000g / 176.4 fl.oz / 11lb:0.4oz / 5000ml
- Minimal Weight: 1g
- Graduation: 1g / 0.1 fl.oz / 0.1oz / 1ml
- Weight Units: g / fl.oz / lb:oz / ml
- Power Supply: 1xCR2032
- Auto-OFF Time: 60 Seconds of Non-Operation
- Low battery indication: **Lo**
- Overload Indication: **EEEE**, or **Err**

FUNCTION QUICK REFERENCE

- Turn Scale ON: Touch "ON/OFF/TARE"
- Turn Scale OFF: Touch "ON/OFF/TARE" and hold for about 2 seconds.
- TARE function: When the scale is ON, touch "ON/OFF/TARE" once (do NOT hold it), wait about 1 second for the scale to clear to 0.
- Change UNIT: When the scale is ON, touch "UNIT" to switch your desired unit in **g**, **fl.oz**, **lb:oz**, and **ml**
- If no operation, the scale will turn off automatically in about 60 seconds.


OPERATION INSTRUCTION

I. Weighing

- Place the scale on hard flat even surface.
- Turn the scale ON.
- You can start to weigh when "0" is shown. If it shows a negative value or value rather than "0", use the TARE function to clear to 0.
- Put the weight object onto the center of the platform, the weight result will be shown.

II. UNIT Selection

Touch "UNIT" key to select your desired unit:



III. Weighing with TARE Function

- Scale is ON.
- Place a holder, plate or a container on the platform, touch "ON/OFF/TARE" (do NOT hold it) and wait about 1 second until "0" is shown.
- Put the weight object into the container, screen reading is the object's weight

Note: You can use the TARE function for as many times as you need in one weighing process.

INDICATION MESSAGE

- Low battery indication.

When "**Lo**" is shown, please replace the batteries.

- Overload indication.

When "**EEEE**" or "**Err**" is shown, this indicates it exceeds the maximum allowance weight, please remove the weight object on the scale to protect the sensors.

(**NOTE:** Never place objects exceeding 11 lb (5000 g) on the scale, it can damage the sensors and scale.)

- Negative reading indication.

Under TARE mode, negative reading will be shown when the container is taken off from the platform. You may use the TARE function to clear to 0.

MAINTENANCE AND CARE

- Please use the scale on a flat, level and hard surface free from vibration and drafts, use it at room temperature.
- Please put the weight object in the center of the scale platform to obtain a more accurate weight.
- This scale is not waterproof, do NOT expose to moisture.
- Store your scale in a clean, dry place. Dust, dirt, and moisture can accumulate on the weighing sensors and electronics causing inaccuracy or malfunction.
- Avoid using your scale in close proximity to strong radio wave emitting devices such as cordless phones.
- Gently apply all items to be weighed. Do not drop items onto the weighing platform. Overload protection does not protect the sensor from shock loading.
- If the scale is not to be used for a long period, please remove the batteries,
- Clean the scale with a slightly damp cloth, do NOT immerse the scale body in water or use chemical/abrasive cleaning agents.
- Check the batteries first if you are having any trouble with your scale. This simple step can remedy most scale issues.

WARRANTY

This product is warranted against defects in materials and workmanship for one year from the date purchase, when used in accordance with the instructions provided. This warranty does not cover damages or wear resulting from accident, misuse, abuse, commercial use, or unauthorized adjustment and/or repair.

C8KE INC. shall not be liable for loss of use or any other incidental, consequential or indirect costs, expenses or damages. There are no express warranties except as listed above. This warranty gives you specific legal rights, and you may have other rights which vary from state to state.

Should this product require service (or replacement at our option) while under warranty, please visit website **www.surpahs.com** and submit a support ticket.

SUPPORT

If you have any questions about this product, please visit **www.surpahs.com**, or scan the QR code, find the support link.

Surpahs™, C8KE INC.
DE 19809, USA